

Paper solution :- T0548

T10325 - TE Electronics & Electrical Engg. 01/7
- Sem 5, Rev-2012, CBSS
T0548 - Electrical Machines-II solⁿ

Q. 1 a) Necessary conditions for parallel operⁿ :-


- 1) Polarities must be same
- 2) Voltage rating must be same
- 3) Phase sequence
- 4) Phase shift
- 5) $Z < \frac{1}{kVA}$

b) Operating Principle of 3 ϕ IM :-
Electromagnetic induction principle.

c) Effect of freq^y :-

If freq \downarrow keeping v_t const, core saturation of air gap flux take place.

If freq $\downarrow \Rightarrow X \downarrow \Rightarrow C/h \uparrow$
 $T \uparrow$



$t_1 < t_2 < t_3$

d) Double Field Revolving Theory :-

Dfa

capⁿ of 2 fields
with diagrams

Q 6b) a High torque I.M.

Deep Bar cage motor

OR


Double cage motor

} Any 1

- ① Diagram
- ② Construction
- ③ working




Q 4 a) Shaded pole I.M.



- Self starting motor
- Construction
- Working :- show or explain resultant flux position in space


Q 4 b) Equivalent ckt of 3φ I.M.

① Stator Equivalent ckt




$$R_c = \frac{V_1'}{I_e} \quad , \quad X_m = \frac{V_1'}{I_m}$$


② Rotor ckt model



2.3 a) Scott connection :- Dia



- Explanation about diagram
- phasor diagram



$$V_{BC} = V_L \angle 0^\circ, V_{CA} = V_L \angle -120^\circ, V_{AD} = V_L \angle 120^\circ$$

Prove :- $V_{AD} = 0.866 V_L \angle 90^\circ$

d) Open delta :-
Diagram


prove $\frac{VV \text{ capacity}}{\Delta \Delta \text{ capacity}} = 57.7\%$

Q2a) Cogging :-
 defn :- magnetic locking - 3 marks
 how to eliminate - skewed bar - 1 mark

Crawling :- 6 Marks

defn :- 2m
 reason - 2m
 diagram - 2m

Q2b) Speed Torque char.



① Motoring zone :- $0 < s \leq 1$

$N_r < N_s$, Motoring action

② Braking zone $s > 1$

plugging, motor must be disconnected.

③ Generative zone $s < 0$

Voltage source is essential for generative mode.

Receives reactive power from supply mains

$$\begin{aligned} \text{Total } B &= 1500 \angle \cos^{-1} 0.8 \\ &= 1500 \angle 36.87^\circ \\ &= 1200 - j900 \end{aligned}$$

$$P_A + 2B = 0.004 + j0.021 \text{ W}$$

$$= 0.021377 \angle 79.215^\circ$$

$$2B = 0.002 + j0.012$$


$$= 0.00932 \angle 79.47^\circ$$

$$= 0.002 + j0.009$$

$$2A = \frac{1000}{500} \times (0.004 + j0.018)$$

8.5 b) Base kVA = 1000

- 3 phase groups
- 1) group No: 1 = 0° phase shift
 - 2) group No: 2 = 180° phase shift
 - 3) group No: 3 = 30° phase shift
 - 4) group No: 4 = 30° phase shift
- Phasor group 1 connectors



$$Q_B = Q \times \frac{Z_A}{Z_A + Z_B}$$

$$= 1500 \angle -36.87^\circ \times \frac{0.00922 \angle 77.47^\circ}{0.021377 \angle 79.215^\circ}$$

$$Q_B = \frac{635.28 \angle -38.61^\circ}{496.415 - j396.425}$$

Load shared by $X^{mer} A$

$$Q_A = Q - Q_B$$

$$= 1200 - j900 - 496.415 - j396.425$$

$$= 703.585 - j503.575$$

$$= 865 \angle -35.6^\circ$$

$$\cos \phi_A = \cos 35.6 = 0.813 \text{ lag.}$$

$$\cos \phi_B = \cos 38.6 = 0.7814 \text{ lag.}$$

$$Q_A = 865 \angle -35.6^\circ \text{ KVA} //$$

$$Q_B = 635.28 \angle -38.61^\circ \text{ KVA} //$$

Q6a) Need of starter :-

- When started from rest, behaves like a $3\phi X^{mer}$ with IT^y shorted.
- If started heavy c/n flows, damage the motor if it is flows for a long time due to high inertia of the rotor. Moreover a high c/n will produce a more voltage drop in line.

Explain Any 1 starter in detail with dia & construction & working.